42-4041 addendum.fm Page 1 Wednesday, August 4, 1999 12:54 PM

ADDENDUM

Electronic Keyboard

Cat. No. 42-4041

Step 8 of “Step Recording” on Page 35 of the Owner's Manual is incorrect. The correct instruction should read:

8. For each additional chord you want to enter, play the chord and use the number buttons to specify its length.

© 1999 Tandy Corporation.
All Rights Reserved.
RadioShack is a registered trademark used by Tandy Corporation.

RadioShack
A Division of Tandy Corporation
Fort Worth, Texas 76102

08A99

Printed in Mexico